

TO ALL TALON OWNERS AND ONWERS THAT HAVE MADE CONVERSIONS TO THE TAIL ROTOR SHAFT DRIVE

Mandatory Compliance Bulletin # M-25

September 10, 2008

History:

The Talon aircraft model has a shaft drive tail rotor system. The gearboxes are mounted to the tailboom bulkheads using 4 mounting studs and nuts on each gearbox. There may be reason that the front gearbox requires a shim to be installed in order to ensure proper gearbox alignment. If a shim is required it can put strain on the gearbox mounting studs. For the first Talon kits or conversions supplied, the mounting studs used were gold in color. A few of these studs have not met specification at the Rotorway South Africa facility.

Action:

RotorWay International is sending replacement mounting studs to the owners of the Talon aircraft. If you find that your aircraft has the gold colored mounting studs and you have not received the new studs please contact our parts department at 480-961-1001. The new studs are black in color. Please do not operate the aircraft until this bulletin has been complied with.

Phone: 480.961.1001 Fax: 480.961.1514 www.RotorWay.com